

Inspection Report



Establishment Name:	King Power Stadium
Establishment Address:	Filbert Way, Leicester LE2 7FL
Food Business Operator:	Compass Contract Services (UK) Limited

Reference:	12/00115/CP
Date:	3 April 2013
Inspection Date:	6 March 2013
Next Inspection:	September 2014

Inspector:	
Telephone:	0116
Fax:	0116
E-mail:	@leicester.gov.uk

This report is issued following the inspection carried out of the Compass catering operation at King Power stadium on 5th March 2013 and the subsequent revisits carried out on the 6th and 12th of March 2013.

Matters detailed in this report were found to be outstanding on my last visit of 12th March 2013. These matters were highlighted on this visit to and I understand that they were addressed shortly after my visit.

Following the inspection, according to the Food Hygiene Rating Scheme, I rated your overall catering operation at the stadium as **5 - Very Good**. For information about how your score was calculated, to appeal or to request a re-rating see the leaflet enclosed with this report entitled 'Your Food Hygiene Rating' or look at food.gov.uk/ratings.

Please display the enclosed certificate in a prominent place inside your establishment and the sticker on your front door or window.

The items listed in this report are contraventions of current legal requirements, except where indicated as **Advice**. The contraventions should be put right within the timescales indicated, which begin on the date that you receive this report.

For further information and advice about food safety, visit www.leicester.gov.uk/food or contact me directly.

No.	Regulation	Contravention	Action Required	Timescale
Structure of kiosks				
1	Regulation (EC) No 852/2004 Annex II Chapter I Paragraph 1	Some maintenance matters were identified in some of the kiosks;	Maintain the kiosk in good repair and condition by;	Immediately
		East 8 (Wellers)		
		<ul style="list-style-type: none"> Loose sealant at skirting board/wall junction. 	<ul style="list-style-type: none"> Remove loose sealant and re-seal. 	
		East 7 (Rowleys)		
		<ul style="list-style-type: none"> Piece cut out of skirting board On front wall acting as dirt trap. 	<ul style="list-style-type: none"> Fill the gap with a piece of wood and seal in place 	
		North 4 (Hines)		
		<ul style="list-style-type: none"> Gaps were evident around pythons passing through the ceiling of the cellar here. 	<ul style="list-style-type: none"> Fill the gaps with expanding foam 	
		North 2 (Filberts donuts)		
		<ul style="list-style-type: none"> Coving loose around the solid pillar by the door acting as dirt trap. 	<ul style="list-style-type: none"> Re-attach the loose coving 	
		West 1 (Shiltons)		
		<ul style="list-style-type: none"> Gaps had opened up in the skirting board around the solid pillar by the door to the cash office which were acting as dirt traps. 	<ul style="list-style-type: none"> Fill the gaps in the skirting board 	

No.	Regulation	Contravention	Action Required	Timescale
Cleaning and Maintenance				
2	Regulation (EC) No 852/2004 Annex II Chapter I Paragraph 1	A few old droppings were noted on the floor in the walk-in chiller in the kiosk store room.	Remove all old droppings and thoroughly clean and disinfect the floor.	Immediate
Advice		Sweeping is not always effective at removing dirt and debris. Using vacuum cleaners is recommended as a more effective method of removing old droppings.		
Store room for Kiosks				
Advice		Best practice is to ensure that all stock is kept in sealed containers at all times and that all stock is stored off the floor on pallets or racking. This will then allow pest checks and effective cleaning to occur.		