

STREET	ADDRESS	WARD	JOB ISSUED	COMPLETED	DESCRIPTION	JOBNVREF	JOBN0	LOCATIONS
EVINGTON VALLEY ROAD	opp /c 14	SPINN	21/09/2006	25/09/2006	'FOOTWAY RELAY SLABS COMBINED RATE "FOOTWAY REPLACE SLABS COMBINED RATE (1x 900 x 600 & 2 x 600 x 600 required)	F/SL	1072	1
EVINGTON VALLEY ROAD	Just past /c 19	SPINN	21/09/2006	27/10/2006	'FOOTWAY RELAY SLABS COMBINED RATE'	F/SL	1067	2
EVINGTON VALLEY ROAD	opp /c 20	SPINN	21/09/2006	30/10/2006	'FOOTWAY REPLACE SLABS COMBINED RATE (1 x 900 x 600 new slab required)'FOOTWAY RELAY SLABS COMBINED RATE'	F/SL	1071	2
EVINGTON VALLEY ROAD	OUTSIDE ENTRANCE TO SCHOOL	SPINN	01/12/2006	05/12/2006	'CARRIAGEWAY REPLACE PCC KERBS - TRAFFIC ISLANDS ETC' 'CARRIAGEWAY RELAY PCC KERBS - TRAFFIC ISLANDS ETC' THESE KERBS ARE	C/KBC	2437	1
EVINGTON VALLEY ROAD	OUTSIDE THE SCHOOL ENTRANCE	SPINN	01/12/2006	05/12/2006	'FOOTWAY RELAY SLABS COMBINED RATE' 'REPLACE 1x750 x 600 AND 1x 600	F/SL	2436	2
EVINGTON VALLEY ROAD	LAMP COLUMN 1	SPINN	01/12/2006	05/12/2006	'FOOTWAY RELAY SLABS COMBINED RATE'	F/SL	2438	1
EVINGTON VALLEY ROAD	near entrance to Hallams site	SPINN	16/03/2007	19/04/2007	'FOOTWAY RE-ERECT BOLLARD' 'FOOTWAY BITMAC PATCH 60MM THICK COMBINED RATE' 'FOOTWAY REMOVE SLABS & REPLACE WITH	F/BOL	4279	3
EVINGTON VALLEY ROAD	OPP LAMP COLUMN 14	SPINN	16/03/2007	27/04/2007	'FOOTWAY RELAY GRANITE KERBS' 'FOOTWAY RELAY SLABS COMBINED RATE'	F/XBG	4280	3
EVINGTON VALLEY ROAD	Opp lamp column 20	SPINN	24/09/2007	13/11/2007	'FOOTWAY NON SCHEDULE OF RATES WORKS' 'Remove slabs replace base course' 'Remove approx 4m2 slabs replace base course' 'Remove	F/NS	7083283	3
EVINGTON VALLEY ROAD	By bus stop	SPINN	13/03/2008	14/03/2008	'FOOTWAY UNEVEN OR BROKEN SLABS - MAKE SAFE BY REMOVING SLABS & REPLACING WITH BITMAC' PLEASE FORWARD THE JOB CARD	F/SL	7085673	1
EVINGTON VALLEY ROAD	Opposite lamp column 14	SPINN	27/03/2008	07/04/2008	'FOOTWAY UNEVEN OR BROKEN SLABS - MAKE SAFE BY REMOVING SLABS & REPLACING WITH BITMAC' 'FOOTWAY - BITMAC PATCH OR	F/SL	7085776	1
EVINGTON VALLEY ROAD	Opposite lamp column 14	SPINN	09/04/2008	10/04/2008	'FOOTWAY NON SCHEDULE OF RATES WORKS' BARRIER OFF FOOTWAY ON EVINGTON VALLEY ROAD. I HAVE LEFT A MESSAGE WITH HALLAMS TO CONTACT ME ABOUT THIS ISSUE & WILL LIAISE WITH [REDACTED] OVER CONSTRUCTING A TEMPORARY HEAVY DUTY CROSSING. PLEASE FORWARD YOUR JOB CARD TO [REDACTED] WHO HAS SITE BASED PHOTOGRAPHS.	F/NS	8090140	1
EVINGTON VALLEY ROAD	o/s Madina School	SPINN	17/06/2008	20/06/2008	'FOOTWAY NON SCHEDULE OF RATES WORKS' 'REMOVE ALL BROKEN & DANGEROUS SLABS AND REPLACE WITH BITMAC AS DISCUSSED WITH [REDACTED] APPROX AREA 20 - 25M2. RISK ASSESSMENT ATTACHED. PLEASE FORWARD JOB CARD TO [REDACTED] COVERING FOR [REDACTED]. REPAIRS TO BE RECHARGED.	F/NS	8090755	1
EVINGTON VALLEY ROAD	o/s Madina School.	SPINN	17/06/2008	20/08/2008	'FOOTWAY NON SCHEDULE OF RATES WORKS' 'SUPPLY SIGNS AND BARRIERS TO PROTECT THE PUBLIC FROM EXTREMELY DANGEROUS FOOTWAY WHICH HAS BEEN CROSSED OVER TO ACCESS SCHOOL. SUBSEQUENT ORDER TO BE ISSUED FOR REMEDIAL WORKS. REMOVE SIGNS AND BARRIERS WHEN THIS REMEDIAL WORK HAS BEEN COMPLETED. THIS TRAFFIC MANAGEMENT WAS PLACED OUT BY RRT LAST WEEK. TO BE RECHARGED.	F/NS	8090754	1
EVINGTON VALLEY ROAD	Opp lamp col 17	SPINN	22/09/2008	29/09/2009	'CARRIAGEWAY POTHOLE - PATCH OR MAKE SAFE' 'FOOTWAY UNEVEN OR BROKEN SLABS - MAKE SAFE BY REMOVING SLABS &	C/BM	8091816	3
EVINGTON VALLEY ROAD	o/s Madani High School	SPINN	24/03/2009	26/03/2009	'REPLACING WITH BITMAC' 'FOOTWAY POTHOLE - PATCH OR MAKE SAFE WITH BITMAC'	F/SL	8094084	1
EVINGTON VALLEY ROAD	(outside Madani High School) Nr Jtn Ethel Road	SPINN	24/09/2010	28/09/2010	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	10112925	2
EVINGTON VALLEY ROAD	Opp Madani High School(L/col 15A)	SPINN	19/09/2011	04/10/2011	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	11122960	1
EVINGTON VALLEY ROAD (Pt addl)	Crossing opp Madani College	SPINN	24/11/2011	05/12/2011	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC' 'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	F/BM	11124411	2
EVINGTON VALLEY ROAD	Opp lamp col 22	SPINN	04/09/2012	09/09/2012	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	12134111	1
EVINGTON VALLEY ROAD	o/s Empire Foodstore	SPINN	04/09/2012	13/09/2012	'F/W DRAINAGE CHANNEL REPLACE WITH NEW' 'F/W DRAINAGE CHANNEL RELAY'	F/CH	12133410	2
EVINGTON VALLEY ROAD	Opp The High School	SPINN	07/03/2013	14/03/2013	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	12137220	1
EVINGTON VALLEY ROAD	Jtn Gwendolen Rd	SPINN	06/09/2013	17/09/2013	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	13143695	2
EVINGTON VALLEY ROAD	Os Super Bros Ltd. Cone On Site Pls Remove On Completion	SPINN	24/02/2014	03/03/2014	'F/W PATCH 60MM'	F/BM	13147828	1
EVINGTON VALLEY ROAD	Os Super Bros Ltd	SPINN	24/02/2014	27/02/2014	'C/W PATCH 100MM'	C/BM	13147829	1
EVINGTON VALLEY ROAD (Pt addl)	Opp Madani College Entry	SPINN	02/06/2014	18/06/2014	'C/W REPLACE PCC CHAN	C/CH	14151306	1
EVINGTON VALLEY ROAD (Pt addl)	Jtn Chesterfield Rd. To Cover	SPINN	02/06/2014	17/07/2014	'C/W PATCH 100MM'	C/BM	14151307	1
EVINGTON VALLEY ROAD	Jtn Ethel Rd. New Edging. Accom Works As Nec	SPINN	25/02/2015	12/03/2015	'F/W LAY TACTILE SLABS	F/SLT	14157219	1
EVINGTON VALLEY ROAD	Outside Madani School	SPINN	27/08/2015	03/09/2015	'C/W PATCH 100MM'	C/BM	15163094	2
EVINGTON VALLEY ROAD	Opp Jtn Marina Road	SPINN	01/03/2016	21/03/2016	'C/W PATCH 100MM'	C/BM	15167231	1
EVINGTON VALLEY ROAD (Pt addl)	Opposite Madani Schools Federation	SPINN	02/06/2016	07/06/2016	'F/W PATCH 60MM'	F/BM	15171488	1
EVINGTON VALLEY ROAD	Between lamp col 22 & bus stop 2 locations / 2 x covers	SPINN	31/08/2016	06/09/2016	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	F/BM	16173166	1
EVINGTON VALLEY ROAD (Pt addl)	O/S Madani Schools Federation Outside the Pedestrian Entrance	SPINN	29/05/2018		'CARRIAGEWAY PATCH 100MM AND REINSTATE WHITE LINING'	C/BM	18201761	1
EVINGTON VALLEY ROAD (Pt addl)	Junction Ethel Road	SPINN	29/05/2018		'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	18201763	1
EVINGTON VALLEY ROAD	Outside 23	SPINN	15/06/2018	15/06/2018	'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' THIS IS A RECHARGE AFTER RTA - PASSED TO [REDACTED] ON 15.06.18 AND REPAIRED SAME DAY BY RRT	F/SL	18202456	1
EVINGTON VALLEY ROAD	Outside Western Power Sub Station near Supra House	SPINN	10/09/2018		'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC' 'Footway pothole next to CATV chambers - range [REDACTED] to make safe/repair	F/BM	18205097	1
EVINGTON VALLEY ROAD	Opposite Western Power Sub Station near Supra House Near bus stop	SPINN	10/09/2018		'C/W POTHOLE 100MM PATCH OR MAKE SAFE' several carriageway potholes on diagonal trench 3+3+3+3+12	C/BM	18205095	1
EVINGTON VALLEY ROAD	Opposite Supra House next to utility box	SPINN	10/09/2018		'C/W POTHOLE 100MM PATCH OR MAKE SAFE' carriageway pothole next to utility box 3+3+3+3+12	C/BM	18205096	1
EVINGTON VALLEY ROAD	Outside Western Power Sub Station	SPINN	19/03/2019	26/03/2019	'C/W POTHOLE 100MM PATCH OR MAKE SAFE' 'Carriageway pothole repair in trench 3+3+3+3+12	C/BM	18211217	1
EVINGTON VALLEY ROAD (Pt addl)	Outside garages near pedestrian crossing	SPINN	17/06/2019	24/06/2019	'and is lying on the footway near the pedestrian crossing area 3+2+3+8	F/BOL	19202146	1
EVINGTON VALLEY ROAD	outside the garage 81 near pedestrian crossing	SPINN	25/09/2019	27/09/2019	'F/W BOLLARD RE-ERECT OR MAKE SAFE BY REMOVING AND REPLACING WITH BITMAC. 'repair leaning/loose cast iron bollard on footway near the pedestrian crossing area 3+2+3+9	F/BOL	19205235	1
EVINGTON VALLEY ROAD	Near Gwendolen Road junction next to gully	SPINN	17/03/2020	24/03/2020	'C/W POTHOLE 100MM PATCH OR MAKE SAFE' 'carriageway pothole repair next to gully with reinstatement of yellow lines 3+3+3+4+13	C/BM	19211428	1
EVINGTON VALLEY ROAD	Opp Supra Bros Building near car park entrance by lamp column 22	SPINN	26/08/2020	16/09/2020	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC' 'Repair footway sinkage near car park entrance by lamp column 22 +2+2+6	F/BM	20212232	1
EVINGTON VALLEY ROAD	Outside entrance to Jacks near Western Power sub station	SPINN	26/08/2020	26/09/2020	'C/W CONC KERBS UNEVEN/ROCKING RELAY PCC KERBS OR MAKE SAFE BY REPLACING WITH BITMAC - TRAFFIC ISLANDS ETC' 'Relay 2 x concrete kerbs and replace 1 x flat broken concrete kerb - 3 areas at location 2+3+3+2+10	C/KBC	20212233	1
EVINGTON VALLEY ROAD (Pt)	OPP. 53	STONE	25/09/2006	27/09/2006	'FOOTWAY RELAY SLABS COMBINED RATE' 'FOOTWAY RELAY GRANITE KERBS' 'FOOTWAY MORTAR REPAIR - AROUND COVERS, KERBS' 'FOOTWAY RELAY SLABS COMBINED RATE'	F/BOL	1109	4
EVINGTON VALLEY ROAD (Pt)	OPP. 47	STONE	25/09/2006	03/10/2006	'FOOTWAY BITMAC PATCH 60MM THICK COMBINED RATE'	F/BM	1110	2
EVINGTON VALLEY ROAD (Pt)	OPPOSITE 34 OUTSIDE SCHOOL	STONE	03/11/2006	03/11/2006	'FOOTWAY RELAY SLABS COMBINED RATE' 'FOOTWAY REPLACE SLABS COMBINED RATE' 'REPLACE 1x750 x 600 REPLACE 1x900	F/BOL	1900	3
EVINGTON VALLEY ROAD (Pt)	OPPOSITE 53	STONE	08/02/2007	12/02/2007	'FOOTWAY RE-ERECT BOLLARD' 'FOOTWAY ADJUST STOP TAP OR HYDRANT COVER' 'RESET UTILITY BOX IN FOOTWAY	F/BOL	3512	2
EVINGTON VALLEY ROAD (Pt)	OUTSIDE SCHOOL OPPOSITE 10	STONE	08/02/2007	19/03/2007	'FOOTWAY RELAY SLABS COMBINED RATE' 'FOOTWAY - RAKE OUT & REGROUT SLABS' 'FOOTWAY MORTAR REPAIR - AROUND COVERS, KERBS' 'FOOTWAY RELAY SLABS COMBINED RATE'	F/SL	3511	5
EVINGTON VALLEY ROAD (Pt)	21	STONE	08/02/2007	26/03/2007	'FOOTWAY RELAY SLABS COMBINED RATE' 'FOOTWAY REPLACE SLABS COMBINED RATE' 'REPLACE 1x900 2x750 2x600 REPLACE 1x900	F/SL	3508	5
EVINGTON VALLEY ROAD (Pt)	Opp 53	STONE	03/08/2007	15/08/2007	'FOOTWAY BITMAC PATCH 60MM THICK COMBINED RATE'	F/BM	7082286	2
EVINGTON VALLEY ROAD (Pt)	12	STONE	03/08/2007	08/08/2007	'FOOTWAY RELAY SLABS COMBINED RATE'	F/SL	7082285	1
EVINGTON VALLEY ROAD (Pt)	THE JUNCTION EVINGTON DRIVE ON THE MINI ROUNDABOUT	STONE	11/10/2007	15/10/2007	'CARRIAGEWAY PATCH 100MM THICK COMBINED RATE'	C/BM	7083694	1
EVINGTON VALLEY ROAD (Pt)	outside school exit	STONE	05/02/2008	07/02/2008	'FOOTWAY UNEVEN OR ROCKING KERBS - MAKE SAFE BY RE-ERECTING OR REPLACING WITH BITMAC' 1 loose concrete kerb o/s school exit needs relaying 2 x loose concrete kerbs plus 1 x granite cobble brick needs relaying	F/KBC	7085221	2
EVINGTON VALLEY ROAD (Pt)	outside Digiprint opp 53	STONE	26/02/2008	26/02/2008	'carried out by [REDACTED]	F/BOL	7085479	1
EVINGTON VALLEY ROAD (Pt)	Opp 29 Os ent to Laya	STONE	29/07/2008	05/08/2008	'FOOTWAY POTHOLE - PATCH OR MAKE SAFE' 'FOOTWAY POTHOLE - PATCH OR MAKE SAFE WITH BITMAC'	C/BM	8091118	2
EVINGTON VALLEY ROAD (Pt)	Nr Bobats Cash & Carry Next to lamp col 8	STONE	29/07/2008	31/07/2008	'FOOTWAY POTHOLE - PATCH OR MAKE SAFE WITH BITMAC'	F/BM	8091119	1
EVINGTON VALLEY ROAD (Pt)	Os Leicester Digital Print (Opposite 51) near entrance	STONE	28/04/2009	01/05/2009	'FOOTWAY DAMAGED BOLLARD - MAKE SAFE BY RE-ERECTING BOLLARD OR REMOVING AND REPLACING WITH BITMAC. 'indirect bollard unrooted onto footway	F/BOL	9100291	1
EVINGTON VALLEY ROAD (Pt)	Os Laya Recreation Centre (Opp 25)	STONE	13/08/2009	17/08/2009	'CARRIAGEWAY POTHOLE - PATCH OR MAKE SAFE' 'CARRIAGEWAY NON SCHEDULE OF RATES WORKS'	F/BOL	9101884	1
EVINGTON VALLEY ROAD (Pt)	Os Laya Recreation Centre Near edge of dropped kerb	STONE	13/08/2009	08/09/2009	'FOOTWAY POTHOLE - PATCH OR MAKE SAFE WITH BITMAC'	F/BM	9101885	1
EVINGTON VALLEY ROAD (Pt)	Os Leicester Digital Print (opp 53)	STONE	13/08/2009	14/08/2009	'FOOTWAY DAMAGED BOLLARD - MAKE SAFE BY RE-ERECTING BOLLARD OR REMOVING AND REPLACING WITH BITMAC.'	F/BOL	9101883	1
EVINGTON VALLEY ROAD (Pt) Addl	os 'out' entrance to School	STONE	18/11/2009	03/12/2009	'F/W UNEVEN/ROCKING KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1 x kerbstone rocking plus 1 x broken/raised kerbstone' 'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1 x 900 and 1 x 600 raised near school fence' 1 x broken kerbstone rocking/raised and x kerbstone raised/rocking' 'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/KBC	9103611	4
EVINGTON VALLEY ROAD (Pt)	Opposite 51 (outside entrance)	STONE	08/02/2010	15/02/2010	'F/W BROKEN KERBS REPLACE WITH NEW OR MAKE SAFE BY REPLACING WITH BITMAC' 1m x corner kerbstone broken/dislodged	F/KBC	9105183	1
EVINGTON VALLEY ROAD (Pt)	Os 112	STONE	10/02/2010	16/02/2010	'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1 x 750 sunk next to GPO chambers' 'F/W UNEVEN/ROCKING KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1m x broken kerbstone	F/SL	9105237	2
EVINGTON VALLEY ROAD (Pt) Addl	Evlington Rd junction near roundabout	STONE	29/04/2010	10/05/2010	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	10110651	1
EVINGTON VALLEY ROAD (Pt)	Os 21	STONE	15/07/2010	19/07/2010	'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1 x 600 sunk around STW stop tap chamber	F/SL	10111888	1
EVINGTON VALLEY ROAD (Pt) Addl	@ Banerman Road junction	STONE	15/11/2010	23/11/2010	'F/W UNEVEN/ROCKING GRANITE KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' one x broken kerbstone on pedestrian crossing' 'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/KBG	10113765	2
EVINGTON VALLEY ROAD (Pt)	Os ent Pak Foods Supermarket	STONE	02/02/2011	07/02/2011	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC' 'F/W MORTAR MISSING/BROKEN AROUND COVERS, STREET FURNITURE ETC. MAKE SAFE BY REPLACING WITH NEW MORTAR' 'remove uneven broken mortar and replace with new full fill in the small hole' 'F/W	F/BM	10114968	3
EVINGTON VALLEY ROAD (Pt) Addl	Evlington Road roundabout opposite the Mosque	STONE	20/04/2011	10/05/2011	'UNEVEN/ROCKING KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 3 x broken/rocking kerbstones	F/BM	10114968	3
EVINGTON VALLEY ROAD (Pt) Addl	Near Banerman Road junction os Shop	STONE	20/04/2011	17/05/2011	'F/W POTHOLE 100MM PATCH OR MAKE SAFE' 'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1 x 900 broken/sunk and 1 x 600 broken/rocking' 'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC' pothole around lamp column 10	F/SL	11120478	3
EVINGTON VALLEY ROAD (Pt) Addl	Outside rear ent to 10 & 12	STONE	03/08/2011		'F/W MORTAR MISSING/BROKEN AROUND COVERS, STREET FURNITURE ETC. MAKE SAFE BY REPLACING WITH NEW MORTAR' 'sunken mortar' 'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC' 'F/W GRANITE SETTS UNEVEN/LOOSE RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 'missing mortar/granite sets near edge of footway and mortar repair between two kerb corners on the other side of the footway crossing	F/MISC	11122116	3
EVINGTON VALLEY ROAD (Pt) Addl	Junc Chesterfield Rd	STONE	17/11/2011	18/11/2011	'C/W POTHOLE 40MM PATCH OR MAKE SAFE'	C/BM	11124286	1
EVINGTON VALLEY ROAD (Pt) Addl	Opp 29	STONE	17/11/2011	18/11/2011	'C/W POTHOLE 40MM PATCH OR MAKE SAFE'	C/CO	11124285	1
EVINGTON VALLEY ROAD (Pt) Addl	O/s School Opp 22	STONE	17/11/2011	17/11/2011	'F/W MORTAR MISSING/BROKEN AROUND COVERS, STREET FURNITURE ETC. MAKE SAFE BY REPLACING WITH NEW MORTAR'	F/MISC	11124283	1
EVINGTON VALLEY ROAD (Pt) Addl	Nr U/col 2	STONE	17/11/2011	24/11/2011	'F/W UNEVEN/BROKEN SLABS REMOVE SLABS & REPLACE WITH BITMAC TO MAKE SAFE'	F/SL	11124284	1
EVINGTON VALLEY ROAD (Pt) Addl	Outside entrance to School	STONE	25/01/2012	10/02/2012	'F/W UNEVEN/ROCKING KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1m x rocking kerbstone	F/KBC	11125600	1
EVINGTON VALLEY ROAD (Pt)	Os 23	STONE	09/02/2012	20/02/2012	'F/W MORTAR MISSING/BROKEN AROUND COVERS, STREET FURNITURE ETC. MAKE SAFE BY REPLACING WITH NEW MORTAR' 'sunken mortar plus broken half 600 with gap and half metre x sunken kerbstone' 'F/W UNEVEN/ROCKING GRANITE KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1m x loose granite kerbstone plus mortar repair next to it' 'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/MISC	11126035	3
EVINGTON VALLEY ROAD (Pt)	Opp 42 (outside school)	STONE	09/02/2012	19/02/2012	'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1 x 900 raised' 'F/W MORTAR MISSING/BROKEN AROUND COVERS, STREET FURNITURE ETC. MAKE SAFE BY REPLACING WITH NEW MORTAR' 'remove metal post piece from slabs and replace with mortar and fill up hole next it	F/SL	11126036	2
EVINGTON VALLEY ROAD (Pt) Addl	At Evington Dr/Evlington Valley roundabout	STONE	15/05/2012	21/05/2012	'C/W POTHOLE 40MM PATCH OR MAKE SAFE' 2 x carriageway potholes	C/BM	12130912	1
EVINGTON VALLEY ROAD (Pt) Addl	Outside Ext ent to Pak Foods	STONE	15/05/2012	18/05/2012	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	12130909	2
EVINGTON VALLEY ROAD (Pt) Addl	Near Pak goods exit entrance	STONE	15/05/2012	21/05/2012	'F/W UNEVEN/ROCKING GRANITE KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1m x raised kerb	F/KBG	12130908	1
EVINGTON VALLEY ROAD (Pt) Addl	Near Mervyn Road	STONE	15/05/2012	22/05/2012	'F/W UNEVEN/ROCKING GRANITE KERBS RELAY OR MAKE SAFE BY REPLACING WITH BITMAC' 1m x loose broken/raised kerb	F/KBG	12130910	1
EVINGTON VALLEY ROAD (Pt) Addl	Opp 12	STONE	15/05/2012	18/05/2012	'F/W GAPS IN SLABS RAKE OUT & REGROUT SLABS' 'Grout in bet kerb and slab	F/MISC	12130913	1
EVINGTON VALLEY ROAD (Pt) Addl	Near out entrance to Pak Foods	STONE	01/08/2012	06/08/2012	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	12132719	1

Address	Details	Material	Date	Description	Category	Value	Count
EVINGTON VALLEY ROAD (Pt) Addl	Os 21	STONE	30/10/2012	'F/W MORTAR MISSING/BROKEN AROUND COVERS, STREET FURNITURE ETC. MAKE SAFE BY REPLACING WITH NEW MORTAR'	F/MISC	12134646	1
EVINGTON VALLEY ROAD (Pt)	Opp 29 outside entrance	STONE	30/01/2013	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	12136302	1
EVINGTON VALLEY ROAD (Pt)	Outside ent to Pak Foods	STONE	30/02/2013	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	12136301	1
EVINGTON VALLEY ROAD (Pt) Addl	At Bannerman & Mervyn Rd junc	STONE	25/04/2013	'C/W LINING WHITE REINSTATE'	C/LIN	13340515	1
EVINGTON VALLEY ROAD (Pt)	around manhole cover	STONE	07/08/2013	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	13143072	1
EVINGTON VALLEY ROAD (Pt) Addl	Opp 29	STONE	18/11/2013	'C/W PATCH 100MM'	C/BM	13145502	1
EVINGTON VALLEY ROAD (Pt)	Os 45	STONE	04/02/2014	'C/W PATCH 100MM'	C/BM	13147378	2
EVINGTON VALLEY ROAD (Pt)	Nr Mervyn Rd Junc - 2xcw Potholes	STONE	29/07/2014	'C/W PATCH 100MM'	C/BM	14152584	1
EVINGTON VALLEY ROAD (Pt)	Os School Opp 34	STONE	29/07/2014	'F/W RELAY SLABS'	F/SL	14152585	2
EVINGTON VALLEY ROAD (Pt)	Os Donation Point Nr Bannerman Rd	STONE	29/07/2014	'U/R G KERBS AND SLABS'	F/KBG	14152586	2
EVINGTON VALLEY ROAD (Pt)	Os School No Entry Entrance Opp 24	STONE	26/01/2015	'F/W RELAY PCC KERBS'	F/KBC	14156403	1
EVINGTON VALLEY ROAD (Pt) Addl	Os 58	STONE	20/05/2015	'C/W PATCH 100MM'	C/BM	15161107	3
EVINGTON VALLEY ROAD (Pt) Addl	Os Pak Foods Entrance Opp 53	STONE	20/05/2015	'F/W RELAY GRANITE KERBS'	F/KBG	15161106	2
EVINGTON VALLEY ROAD (Pt)	Os School Fence Opp 40	STONE	16/07/2015	'F/W RELAY SLABS'	F/SL	15162265	3
EVINGTON VALLEY ROAD (Pt) Addl	Os Pak Foods Opp Evington V Grdhs	STONE	13/11/2015	'C/W PATCH 100MM'	C/BM	15164742	2
EVINGTON VALLEY ROAD (Pt) Addl	Os School Opp 34	STONE	13/11/2015	'F/W RELAY SLABS'	F/SL	15164743	1
EVINGTON VALLEY ROAD (Pt)	Os 29	STONE	03/02/2016	'C/W RELAY GRANITE SETT'	C/GS	15166491	2
EVINGTON VALLEY ROAD (Pt)	Opp 25	STONE	03/02/2016	'C/W RELAY GRANITE SETT'	C/GS	15166497	1
EVINGTON VALLEY ROAD (Pt)	At Mervyn Rd Junction	STONE	03/02/2016	'C/W PATCH 100MM & REINS W LINE'	C/BM	15166496	2
EVINGTON VALLEY ROAD (Pt)	Os 4	STONE	03/02/2016	'F/W RELAY SLABS'	F/SL	15166494	1
EVINGTON VALLEY ROAD (Pt) Addl	By Chesterfield Rd junction near pedestrian crossing	STONE	16/05/2016	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	16171141	1
EVINGTON VALLEY ROAD (Pt)	Opp Mervyn Road junction around utility box	STONE	13/07/2016	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	16172397	1
EVINGTON VALLEY ROAD (Pt)	Os School Opposite 32	STONE	13/07/2016	'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC'	F/SL	16172398	1
EVINGTON VALLEY ROAD (Pt) Addl	Os 58	STONE	14/11/2016	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	16174567	1
EVINGTON VALLEY ROAD (Pt) Addl	Outside entrance to Pak Foods Opp 53	STONE	14/11/2016	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	16174566	3
EVINGTON VALLEY ROAD (Pt)	Outside Evington Valley School	STONE	23/12/2016	'CARRIAGEWAY PATCH 100MM AND REINSTATE YELLOW LINE'	C/BM	16175299	1
EVINGTON VALLEY ROAD (Pt)	Outside ent to Pak Foods	STONE	02/02/2017	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	16176055	2
EVINGTON VALLEY ROAD (Pt)	Outside Pak Foods near telephone booth	STONE	02/02/2017	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	16176056	2
EVINGTON VALLEY ROAD (Pt)	Os 40	STONE	02/02/2017	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	16176057	3
EVINGTON VALLEY ROAD (Pt)	Outside School entrance Opp 28	STONE	02/02/2017	'C/W GRAN SETT RELAY CARRIAGEWAY PATCH 100MM AND REINSTATE YELLOW LINE'	C/GS	16176058	2
EVINGTON VALLEY ROAD (Pt)	Opp 36	STONE	03/02/2017	'C/W GRAN SETT RELAY'	C/GS	16176073	1
EVINGTON VALLEY ROAD (Pt)	Os Pak Foods exit entrance	STONE	30/03/2017	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	16177384	1
EVINGTON VALLEY ROAD (Pt) Addl	Opp 2	STONE	02/05/2017	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	17180625	1
EVINGTON VALLEY ROAD (Pt) Addl	Outside Pak Foods	STONE	26/10/2017	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	17183439	3
EVINGTON VALLEY ROAD (Pt) Addl	Os School Opposite nos.12 and 14	STONE	26/10/2017	'F/W SLABS BROKEN REPLACE WITH NEW OR MAKE SAFE BY REPLACING WITH BITMAC'	F/BM	17183440	1
EVINGTON VALLEY ROAD (Pt)	Near Evington Drive junction	STONE	17/02/2018	'C/W POTHOLE 40MM PATCH OR MAKE SAFE'	F/SL	17184703	1
EVINGTON VALLEY ROAD (Pt)	Outside Pak Foods near lamp column 9	STONE	06/02/2018	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	17185203	1
EVINGTON VALLEY ROAD (Pt)	Outside School - opp 10	STONE	06/02/2018	'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC'	F/SL	17185204	1
EVINGTON VALLEY ROAD (Pt) Addl	Opp 6	STONE	04/06/2018	'C/W POTHOLE 40MM PATCH OR MAKE SAFE'	C/BM	18201946	1
EVINGTON VALLEY ROAD (Pt) Addl	Os 52	STONE	04/06/2018	'F/W SLABS BROKEN REPLACE WITH NEW OR MAKE SAFE BY REPLACING WITH BITMAC'	F/SL	18201947	1
EVINGTON VALLEY ROAD (Pt)	Outside Pak Foods (opp 39)	STONE	24/07/2018	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	18203685	1
EVINGTON VALLEY ROAD (Pt)	Near Mervyn Road	STONE	24/07/2018	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	18203686	1
EVINGTON VALLEY ROAD (Pt)	Os 44	STONE	24/07/2018	'F/W MORTAR MISSING/BROKEN AROUND COVERS, STREET FURNITURE ETC. MAKE SAFE BY REPLACING WITH NEW MORTAR'	F/MISC	18203684	1
EVINGTON VALLEY ROAD (Pt)	Outside Pak Foods near the telephone box	STONE	28/01/2019	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	18209530	1
EVINGTON VALLEY ROAD (Pt)	Outside entrance to Talba building opposite 27	STONE	28/01/2019	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	18209531	1
EVINGTON VALLEY ROAD (Pt)	Outside School (opposite 34)	STONE	28/01/2019	'F/W SLABS UNEVEN/ROCKING RELAY OR MAKE SAFE BY REPLACING WITH BITMAC'	F/SL	18209532	1
EVINGTON VALLEY ROAD (Pt)	Outside Pak Foods (opposite 37)	STONE	28/01/2019	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	18209528	1
EVINGTON VALLEY ROAD (Pt)	Outside 45	STONE	28/01/2019	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	18209529	1
EVINGTON VALLEY ROAD (Pt)	Outside Al-Khair Foundation near Bannerman Road	STONE	06/08/2019	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	19203924	1
EVINGTON VALLEY ROAD (Pt)	At Evington Valley Gardens	STONE	06/08/2019	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	19203925	1
EVINGTON VALLEY ROAD (Pt)	outside school near staff and visitors car park entrance opposite 42	STONE	06/08/2019	'F/W UNEVEN/BROKEN SLABS REMOVE SLABS & REPLACE WITH BITMAC TO MAKE SAFE'	F/SL	19203927	1
EVINGTON VALLEY ROAD (Pt)	Near Evington Dr roundabout	STONE	06/08/2019	'F/W BOLLARD RE-ERECT OR MAKE SAFE BY REMOVING AND REPLACING WITH BITMAC'	F/BOL	19203926	1
EVINGTON VALLEY ROAD (Pt)	Outside Pak Foods Opposite Evington Valley Gardens	STONE	04/02/2020	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	19209593	1
EVINGTON VALLEY ROAD (Pt)	Outside Pak Foods next to BT box on new patch	STONE	04/02/2020	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	19209594	1
EVINGTON VALLEY ROAD (Pt)	Near Ethel Road junction near lamp column 11	STONE	04/02/2020	'CARRIAGEWAY PATCH 100MM AND REINSTATE YELLOW LINE'	C/BM	19209592	1
EVINGTON VALLEY ROAD (Pt)	Near 60 around BT box	STONE	21/07/2020	'F/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	20211328	1
EVINGTON VALLEY ROAD (Pt) Addl	At Evington Drive junction	STONE	17/11/2020	'F/W BOLLARD RE-ERECT OR MAKE SAFE BY REMOVING AND REPLACING WITH BITMAC'	F/BOL	20214584	1
EVINGTON VALLEY ROAD (Pt) Addl	Os School Car park entrance	STONE	17/11/2020	'FOOTWAY RENEW CONCRETE KERB AND BITMAC 40MM PATCH'	F/KBC	20214585	1
EVINGTON VALLEY ROAD (Pt)	Outside 22/24	STONE	03/02/2021	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	20216900	1
EVINGTON VALLEY ROAD (Pt)	Outside entrance to Talba (opposite 29)	STONE	03/02/2021	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	20216897	1
EVINGTON VALLEY ROAD (Pt)	Os entrance to School car park Opposite 44	STONE	03/02/2021	'CARRIAGEWAY PATCH 100MM AND REINSTATE YELLOW LINE'	C/BM	20216901	1
EVINGTON VALLEY ROAD (Pt)	Outside entrance to 23	STONE	03/02/2021	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	20216902	1
EVINGTON VALLEY ROAD (Pt)	Outside 60 entrance	STONE	03/02/2021	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	20216898	1
EVINGTON VALLEY ROAD (Pt)	Opposite Al-Khair Foundations near crossroads junction near lamp column 6	STONE	03/02/2021	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	20216899	1
EVINGTON VALLEY ROAD (Pt)	Near Pak Foods near lamp col 8	STONE	03/02/2021	'C/W POTHOLE 60MM PATCH OR MAKE SAFE WITH BITMAC'	F/BM	20216896	1
EVINGTON VALLEY ROAD (Pt)	Near Evington Road	STONE	05/05/2021	'F/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	21221083	1
EVINGTON VALLEY ROAD (Pt) Addl	Opposite 22 near school gate	STONE	11/05/2021	'C/W POTHOLE 100MM PATCH OR MAKE SAFE'	C/BM	21221283	1