

LEICESTER CITY COUNCIL - HIGHWAY MANAGEMENT

HIGHWAY INSPECTION REGISTER

Street : CRAVEN STREET, ABBEY WARD

Inspection Schedules:
11/04/2021 - 11/04/2022

From :

To :

| Inspection Schedule | Inspect. Date | Inspected By | Works Orders | Notes |
|---------------------|---------------|--------------|--------------|------------|
| 001694 | 21/07/2021 | F | | no repairs |

Revision 1.4

Leicester City Council - Highway Management - Works Order

CARRIAGEWAY WORKS

| | | | |
|------------------|-----------------------------|--------------|-------------------------|
| Inspector | | Order Number | 21229563 |
| Urgency Category | CAT 1 URGENT CALLOUT | FMIS Code | R100052N100338 |
| Street Name | CRAVEN STREET | Issued Date | 25-February-2022 |
| Area | ABBAY WARD | Complete by | 26-February-2022 |

| Locations in Street | Size | Work to do |
|-------------------------------------|-------------|---|
| Craven st and Berkley st jct | x no | 'C/W NON SCHEDULE OF RATES WORKS' Make safe called through to The Manhole cover is broken, reported as S81 |

| Item Code | Description of Work | Unit | Quantity |
|-----------|---|------|----------|
| NONSOR C | Non schedule of rates works CARRIAGEWAY | each | 1.00 |

| | |
|-------------------|---------------|
| Total Cost | £ 0.00 |
|-------------------|---------------|

| | |
|--------------------|----------|
| Completed on _____ | By _____ |
|--------------------|----------|

Request Information Target Date 20 Dec 2021

Customer Detail

Request Id 142989

- Councillor Contact - 10 Day
- MP Contact - 10 Days
- OCL - 5 days
- EMail External - 5 Days
- EMail Internal - 10 Days
- Mayor Enquiry - 5 Days
- Mayor's Website - 10 Days
- General CRM - 10 Days

Name

Address

Telephone

Mobile

Email

Date Input 06 Dec 2021

CRM No HW383267430

Created By 67

Client Name

Location CRAVEN STREET

Additional Info

Complaint

Complaint Date

Category Carriageway defect

Target Date 20 Dec 2021

Close Date

Details It is roughly 25-30 yards back from the junction with Sanvey Gate near Wolseley Plumb & Parts in the middle of carriageway closest to Wolseley.

This is a deep pothole in the middle of the carriageway that requires immediate repair as it presents a road hazard. It has already ripped a massively gash in the left-hand side tyre of my car at a low speed when I was approaching the junction with Sanvey Gate. I have many photos but they exceed the upload limit although I am happy to share them with you.

Ward Abbey

Officer I

Team Name Highway Asset Management

REQUEST HISTORY

| Date | Time | User | Details |
|------------|------|------|--|
| 06/12/2021 | | t | Details e-mailed to ' @ 11.00 also rang and spoke to I on mobile @ 11.01 |

Customer contacted? Yes / No Date contacted: _____

Date enquiry/complaint closed _____

Signed _____